

Figure S1




Figure S1. Sample 87C cracked while attempting to measure its Vickers microhardness.